

High conversion efficiency
High reliability
High efficiency
High quality

-
-
-

- Strict incoming material, delivery and package inspection
- Accuracy of efficiency test is controlled within $\pm 0.1\%$
- 100% Full inspection of reverse leakage and cell appearance
- Calibration piece traced to Fraunhofer

